HABS MASS 5-SAL

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Narbonne House 71 Essex Street Salem Essex County Massachusetts HABS No. MA-802

Eric H. Muller, photographer No. 1: August, 1958; Nos. 2-13: August, 1962	
MA-802-1	NORTH SIDE AND WEST FRONT (1958)
MA-802-2	NORTH SIDE AND WEST FRONT (1962)
MA-802-3	WEST FRONT, FROM THE SOUTHWEST
MA-802-4	WEST FRONT AND SOUTH SIDE
MA-802-5	SOUTH SIDE AND EAST REAR
MA-802-6	INTERIOR, FIRST FLOOR, ELEVATION OF STAIRS
MA-802-7	INTERIOR, VIEW OF STAIR WELL, LOOKING DOWN FROM SECOND FLOOR
MA-802-8	INTERIOR, FIRST FLOOR, ROOM NO. 4 (SEE MEASURED DRAWINGS), SOUTH WALL, SHOWING FIREPLACE AND CORNER CUPBOARD
MA-802-9.	INTERIOR, FIRST FLOOR, ROOM NO. 4 (SEE MEASURED DRAWINGS), WEST WALL, SHOWING WINDOWS
MA-802 -1 0	INTERIOR, FIRST FLOOR, ROOM NO. 2 (SEE MEASURED DRAWINGS), WEST WALL, SHOWING WINDOWS AND CORNER CUPBOARD
MA-802-11	INTERIOR, SECOND FLOOR, ROOM NO. 9 (SEE MEASURED DRAWINGS), EAST WALL
MA-802-12	INTERIOR, SECOND FLOOR, ROOM NO. 12 (SEE MEASURED DRAWINGS), NORTH WALL, SHOWING FIREPLACE
MA-802-13	INTERIOR, ATTIC, LOOKING SOUTH
MA-802 -1 4	Photocopy of photograph (source unknown) photographer unknown pre-1885 NORTH SIDE AND WEST FRONT (NOTE ABSENCE OF DORMER ON GAMBREL ROOF OF ELL) (Illustration #6 of Data Report included in Field Records)
MA-802-15	Photocopy of photograph (from Society for the Preservation of New England Antiquities, negative number 2908A) Wilfred A. French, photographer ca. 1885-1895 NORTH SIDE AND WEST FRONT (NOTE ADDITION OF DORMER ON CAMBREL ROOF OF ELL) (Illustration #11 of Data Report included in Field Records)

NARBONNE HOUSE HABS No. MA-802 Index to Photographs Page 2

MA - 802 - 16Photocopy of photograph (from Society for the Preservation of New England Antiquities, negative number 2425B) Wilfred A. French, photographer ca. 1885-1895 EAST REAR AND NORTH SIDE (Illustration #7 of Data Report included in Field Records) MA-802-17 Photocopy of photograph (from the Essex Institute, negative number 214) Frank Cousins, photographer ca. 1891 SOUTH SIDE AND EAST REAR (Illustration #8 of Data Report included in Field Records) MA - 802 - 18Photocopy of photograph (from the Essex Institute, negative number Frank Cousins, photographer ca. 1900 FIRST STORY, DETAIL OF WINDOW (Illustration #10 of Data Report included in Field Records) MA-802-19 Photocopy of photograph (from the Essex Institute, negative number 2270) Frank Cousins, photographer ca. 1900 ELL, SECOND STORY, DETAIL OF WINDOWS (Illustration #9 of Data Report included in Field Records) MA-802-20 Photocopy of photograph (from the Essex Institute, negative number 501) Frank Cousins, photographer 1891 INTERIOR, FIRST FLOOR, ROOM NO. 4 (SEE MEASURED DRAWINGS), SOUTH WALL, SHOWING FIREPLACE AND CORNER CUPBOARD (Illustration #2 of Data Report included in Field Records) MA-802-21 Photocopy of photograph (from the Essex Institute, negative number 502) Frank Cousins, photographer 1891 INTERIOR, FIRST FLOOR, ROOM NO. 4 (SEE MEASURED DRAWINGS), NORTHEAST CORNER (Illustration #3 of Data Report included in Field Records) MA-802-22 Photocopy of photograph (from the Society for the Preservation of New England Antiquities) photographer unknown 1888

MRS. SARAH (VINCENT) NARBONNE SEATED IN ROOM NO. 4 (SEE MEASURED DRAWINGS) (Illustration #1 of Data Report included in Field Records)